


LM510 System restore

The Log Mate 510 computer has a built in restore function. It is possible to restore the computer to the state it had at delivery from Log Max AB. To do a full system restore please follow the instructions below.



1. Turn on the computer by pressing 1. Immediately after 9 is lit, press and hold button 3 until command prompt appears.
2. Wait for Recovery Wizard
3. Read the text carefully before pressing “Backup and Restore”. Then follow the onscreen instructions. To quit the recovery wizard press “Quit”

